
Alert number **[A11/00032/21](#)**

Product **Passenger car**

Risk type **Injuries**

The electrical grounding may be insufficient. This could lead to unexpected side airbag deployment, increasing the risk of injury.

Category **Motor vehicles**

Type **Consumer**

Description **3- and 5- door passenger cars.**

Brand **OPEL**

Name **CORSA F, CORSA e**

EC-type approval/model **e2*2007/46*0639*07 -08-09-11**

Production dates **The affected vehicles were manufactured in 2020 and 2021.**

Company recall code **20-C-192**

Weekly report number **Report-2021-16**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **France**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **22/12/2020**

Products were found and measures were taken also in **Greece
Ireland
Poland**

Alert number **[A12/00533/21](#)**

Product **Costume set**



Risk type **Chemical**

The product's leaf-shaped pendant contains an excessive cadmium content (measured value: 75% by weight). Cadmium is harmful to human health because it accumulates in the body, damages the kidneys and the bones and is carcinogenic.

The product does not comply with the REACH Regulation.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **1920s Flapper set consisting of a hairband with golden leaf-shaped pendants decorated with pearls, pearl necklace, long black gloves and cigarette holder. The product was sold online, in particular via Amazon.**

Brand **BigLion**

Name **Mode 20 Jahre Accessoires Flapper Set Stirnband Ohrringe Perlen Halskette Handschuh Zigarettenspitze**

Batch number **X0012573KH
ASIN: B07C9D1TVW**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **Unknown**

Alert number **[A11/00031/21](#)**

Product **Quadricycle**

Risk type **Fire**

The screws that are connecting the internal power poles to each of the two 51.4 V modules of the electric vehicle's traction battery may be inadequate. This could increase the risk of fire.

Category **Motor vehicles**

Type **Consumer**

Description **Quadricycle**

Brand **AIXAM**

Name **S9**

EC-type approval/model **e2*168/2013*00026*00; Batch Numbers: 2023372 to 2023476**

Production dates **The affected vehicles were manufactured between January and February 2021.**

Company recall code **20210218 M12RS**

Weekly report number **Report-2021-16**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **France**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **01/02/2021**

Alert number **[A11/00030/21](#)**

Product **Quadricycle**

Risk type **Fire**

The screws that are connecting the internal power poles to each of the two 51.4 V modules of the electric vehicle's traction battery may be inadequate. This could increase the risk of fire.

Category **Motor vehicles**

Type **Consumer**

Description **Quadricycle**

Brand **AIXAM**

Name **S9**

EC-type approval/model **Batch numbers: 3216727 to 3223195
e2*168/2013*00027*00**

Production dates **The affected vehicles were manufactured between October 2020 and February 2021.**

Company recall code **20210218 S9**

Weekly report number **Report-2021-16**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **France**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **01/02/2021**

Alert number **[A12/00552/21](#)**

Product **Necklace**



Risk type **Chemical**

The necklace's extender chain releases an excessive amount of nickel (measured value up to 62 µg/cm²/week). Nickel is a strong sensitiser and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin.

The product does not comply with the REACH Regulation.

Category **Jewellery**

Type **Consumer**

Description **3-pack of silver children's necklace with pink pearls and a Swan pendant. The product is also sold online, with 325135010000 as article number.**

Packaging description **The product is sold with an outer packaging consisting of a transparent plastic bag, and an inner packaging consisting of a piece of cardboard to which the necklace and extra rings for the chain are attached to.**

Brand **Star Jewellery**


Name **Halskjede med perler og svane**

Type / number of model **201 Star Jewellery**

Barcode **7333157061604**

Alert number **[A12/00518/21](#)**

Product **Safety gate for children**



Risk type **Injuries**

Due to malfunction of the automatic locking system, the safety gate opens unexpectedly after a short period of use. A child might pass through the opening and fall down the stairs.

The product does not comply with the relevant European standard EN 1930.

Category **Childcare articles and children's equipment**

Type **Consumer**

Description **111 - 118 cm wide metal barrier in combination with dark wood, which contains a 35 cm wide extension. The product was also sold online.**

Packaging description **Cardboard box.**

Brand **Unknown**

Name **PUPYhou**

Type / number of model **XY006**

Weekly report number **Report-2021-16**

Alert submitted by **Czechia**

Is the product counterfeit? **Unknown**

Alert number **[A12/00519/21](#)**

Product **Fall arrester**



Risk type **Injuries**

If the openable side plate is subject to a heavy load, it may cause the locking system to fail, leading to injuries to the user.

The product does not comply with the Personal Protective Equipment Regulation.

Category **Protective equipment**

Type **Consumer**

Description **Personal fall protection system.**

Brand **Climbing Technology**

Name **Easy Speed**

Type / number of model **Ref. N0. 2F714**

Batch number **0120
0220**

Weekly report number **Report-2021-16**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **Italy**

Alert number **[A12/00539/21](#)**

Product **Bunk bed**



Risk type **Entrapment
Injuries
Strangulation**

The product has protruding parts; furthermore, the distance between the slats is inadequate. A child may get trapped and suffer injuries or strangulation if stuck between the slats, or if hitting a protruding part.

The product does not comply with the requirements of the General Product Safety Directive and with the relevant European standard EN 747-1.

Category **Furniture**

Type **Consumer**

Description **Bunk beds, 90 x 190cm, GREY, two levels**

Packaging description **The product is sold packed in a cardboard box. The product was sold online, in particular via CDiscount.**

Brand **ELITE**

Name **COLOSSE - Lits superposés extra durable**


Weekly report number **Report-2021-16**

Alert submitted by **France**

Is the product counterfeit? **Unknown**

Alert number **[A12/00520/21](#)**

Product **Plastic balls**



Risk type **Chemical**

The toy contains an excessive amount of diisobutyl phthalate (DIBP) (measured value up to 30,3% by weight). This phthalate may harm the health of children, causing possible damage to their reproductive system.

The product does not comply with the REACH Regulation and the requirements of the Toy Safety Directive.

Category **Toys**

Type **Consumer**

Description **Set of three plastic balls.**

Packaging description **Net bag.**

Brand **Midex**

Name **Pilka**

Type / number of model **ITEM NO.: D33351**

Barcode **EAN 5900733548389**

Weekly report number **Report-2021-16**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Alert number **[A12/00521/21](#)**

Product **Acivity toy**



Risk type **Chemical**

The fabric material contains the flame retardant tris(2-chlor-1-methylethyl phosphate (TCPP) (measured value: 18,7 mg/kg). TCPP can be harmful to children due to its carcinogenic properties and acute toxicity.

The product does not comply with the requirements of Toy Safety Directive.

Category **Toys**

Type **Consumer**

Description **A toy consisting of six cubes with filling, covered with fabric made of soft PVC.**

Packaging description **Plastic packaging.**

Brand **Gazelo Toys**

Name **Intellect Blocks**

Type / number of model **G137506-b055-7331**


Barcode **EAN 5900949424507**

Weekly report number **Report-2021-16**

Alert submitted by **Poland**

Alert number **[A12/00551/21](#)**

Product **Necklace**



Risk type **Chemical**

The product contains an excessive amount of lead (measured values: up to 0,46 % by weight) and releases an excessive amount of nickel (measured values up to 18 µg/cm²/week). Lead is harmful to human health, accumulates in the body, can cause developmental neurotoxicity and may also affect breast-fed or unborn children. Nickel is a strong sensitiser and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin.

The product does not comply with the REACH Regulation.

Category **Jewellery**

Type **Consumer**

Description **Black textile necklace thread with spherical silvery metal pendant adorned with a big heart overlapping a smaller heart. The product is also sold online.**

Packaging description **The product is sold in a white cardboard box with a transparent plastic display window, and with the drawing of a pregnant woman on it.**

Brand **Babylonia Bola**

Name **Babylonia Bola gravidsmykke dobbelhjerte**


Type / number of model **VF-118**

Alert number

A12/00523/21

Product

Plastic toy with accessories



Risk type

Choking

Small parts (e.g. head or accessories) may easily become detached from the toy. A small child may put them in the mouth and choke.

The product does not comply with the requirements of the Toy Safety Directive and with the relevant European standard EN 71-1.

Category

Toys

Type

Consumer

Description

Set of plastic figures representing unicorns with small accessories.

Packaging description

Plastic blister packaging on coloured cardboard.

Brand

BG INTERNATIONAL

Name

Unicorns

Type / number of model

13748

Batch number

CF180086

Barcode

3588270013748

Weekly report number

Report-2021-16

Alert number **[A11/00027/21](#)**


Product **Extension lead**



Risk type	<p>Electric shock Fire</p> <p>The wire strands can break due to flexing causing sparks This can cause electric shock and fire.</p> <p>The product does not comply with the requirements of the Low Voltage Directive</p>
Category	Electrical appliances and equipment
Type	Consumer
Description	Extension socket set with 4 way surge protected socket outlet with 2 meter cord. The product was also sold online, in particular via Amazon.
Packaging description	Sold in a plastic translucent packaging approximately 300mm x 20mm.
Brand	Pifco
Name	4 Way Surge Protected Extension Lead
Type / number of model	Pif2048
Barcode	5024996704532
Weekly report number	Report-2021-16
Alert submitted by	Malta

Alert number **[A11/00029/21](#)**

Product **Extension lead**



Risk type **Electric shock**

The contacts of the socket offer increased electrical resistance leading to overheating and subsequently exposing live parts, causing risk of electric shock.

The product does not comply with the requirements of the Low Voltage Directive

Category **Electrical appliances and equipment**

Type **Consumer**

Description **2 way extension socket with 3 meter cord**

Packaging description **Packed in transparent hard plastic measuring approx. 250mm x 200mm**

Brand **PowerOn**

Name **Extension Socket**

Type / number of model **Model No.:702N**

Barcode **8204234702217**

Weekly report number **Report-2021-16**

Alert submitted by **Malta**

Is the product counterfeit? **Unknown**

Alert number **[A11/00028/21](#)**

Product **Extension lead**



Risk type **Electric shock
Fire**

**The wire strands can break due to flexing causing sparks
This can cause electric shock and fire.**

**The product does not comply with the requirements of the
Low Voltage Directive.**

Category **Electrical appliances and equipment**

Type **Consumer**

Description **6 way 2 meter cord extension socket with individually
switched sockets.**

Packaging description **Soft plastic transparent packaging measuring
approximately 340mm x 150mm**

Brand **SMJ Electrical (PMS)**

Name **Extension Lead**

Type / number of model **Part No. F6W215 (8618N)**

Barcode **5060038166036**

Weekly report number **Report-2021-16**

Alert submitted by **Malta**

Alert number **[A12/00522/21](#)**

Product **Leather gloves**



Risk type **Chemical**

The leather in the product contains chromium (VI) (measured value: 6 mg/kg). Chromium (VI) is sensitising, can trigger allergic reactions and may cause cancer.

This product does not comply with the REACH regulation.

Category **Clothing, textiles and fashion items**

Type **Consumer**

Description **Dark red leather gloves with three decorative motifs embroidered on the back of the glove and the longer shaft to be folded back, sheepskin lining, size S/M.**

Packaging description **Product supplied without any packaging, only with a label**

Brand **Ashwood Est. 1986**

Name **Fine Leather Gloves**

Type / number of model **071858**

Batch number **19 40 25 071858 7**

Barcode **1940071858001499**


Weekly report number **Report-2021-16**

Alert number

A12/00538/21

Product

Community Face Covering



Omschrijving

[De geprojecteerde foto's van het artikel worden getoond met een achtergrond van een rood kruis op een witte achtergrond.](#)

- De Under Armour Sportsmask geeft je de luchtstroom die je nodig hebt, voor lokal van en is uitbreidbaar geschikt in het sporten.
- Gemakkelijk van 'hoogwaardige' 3D materialen, ontworpen om de hele dag te dragen en tijdens het sporten.
- Geschikt voor gebruik in koude of warme omstandigheden en kan worden gebruikt in alle weersomstandigheden.
- Waterafstotend (waterafstotend) met goede ademende eigenschappen.
- Ademende behouding van de binnenkant om het masker fris te houden.
- Openlijk en ademend materiaal dat niet door maar maakt het makkelijk voor water te dronken.
- Het kan ook gebruikt worden voor de bescherming en veiligheid van het gezicht van de gebruiker.
- Het is geschikt voor gebruik voor comfort en veiligheid van de gebruiker.
- Het is geschikt voor gebruik voor comfort en veiligheid van de gebruiker.

Materiaal Samenstelling: 100% Polyester / 100% Polyester / 100% Polyester / 100% Polyester / 100% Polyester



Risk type

Chemical

The product contains Polyhexanide (PHMB). PHMB is harmful if inhaled and may cause an allergic skin reaction. By inhalation, it causes damage to organs through repeated exposure and is also suspected of causing cancer.

The product does not comply with the Biocidal Products Regulation nor with the requirements of the General Product Safety Directive.

Category

Clothing, textiles and fashion items

Type

Consumer

Description

Black face mask (3 layers) with wide black elastics and white Under Armour logo, sold with a black carrying pouch. Also available in grey. Different sizes available: S/M, M/L, L/XL and XL/XXL. The product is also sold online.

Packaging description

Black opaque plastic bag

Alert number **[A12/00524/21](#)**

Product **Motorcycle**

Risk type **Injuries**

The gear wheels may break due to restrictions on the gear shifting. This could lead to obstruction of the drivetrain, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Motorcycle**

Brand **KAWASAKI**

Name **Ninja H2 SX/ SX SE/ SX SE+**

EC-type approval/model **e4*168/2013*00073*00, *02, Type: ZXT02A**

Production dates **The affected vehicles were manufactured between 2018 and 2019.**

Company recall code **DAJ43**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Greece
Poland
Slovenia**

Alert number

A12/00540/21

Product

Particle filter mask



Risk type

Health risk / other

The particle/filter retention of the material is insufficient (measured value: as low as 82 %). Consequently, an excessive amount of particles or microorganisms might pass through the mask; thus, even if combined with other recommended measures, it may not properly protect.

The product does not comply with the PPE Regulation and the relevant European standard EN 149.

Category

Protective equipment

Type

Consumer

Description

White respiratory protective face mask in a transparent plastic bag (1 piece) with packaging indicating only the KN95 standard; according to the printing on the mask itself, both standard KN95 GB2626-2006 and also EU standard EN 149:2001+A1:2009 are met

Packaging description

Plastic bag with black inscription. The product was sold

Alert number **[A12/00525/21](#)**

Product **Passenger car**

Risk type **Fire**

Fuel may leak as a result of a poorly fitted quick connector on the fuel supply pipe. Fuel leakage close to a source of ignition will increase the risk of fire.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **LAMBORGHINI**

Name **Urus**

EC-type approval/model **e3*KS07/46*0481*, Type 636**

Production dates **The affected vehicles were manufactured between July 2017 and July 2020.**

Company recall code **L636-R.02.20**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Ireland**

Alert number **[A12/00537/21](#)**

Product **Motorcycle**

Risk type **Injuries**

Due to deviations during the heat treatment of the raw material, cracks may occur on the handlebar clamps. Consequently, these cracks could cause the handlebar clamp to break off together with the mounted clip-on handlebars, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Motorcycle**

Brand **KTM**

Name **RC 390 R**

EC-type approval/model **e1*168/2013*00016*01**

Production dates **Model Year 2018**

Weekly report number **Report-2021-16**

Alert submitted by **Austria**

Is the product counterfeit? **No**

Country of origin **Austria**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **31/03/2021**

Company recall code - **<https://www.ktm.com/de-de/service/Safety.html>**

Alert number **[A12/00526/21](#)**

Product **Quad accessory - seat belt**

Risk type **Injuries**

Certain stitchings may be missing on the seat belts. This could lead to increased risk of injury in the event of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Seat belt for quadricycles.**

Brand **CAN-AM**

Name **Maverick**

EC-type approval/model **Part numbers: 715003610, 715006190**

Production dates **October 2017 to July 2020**

Company recall code **2020_6618 5468**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Unknown**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**


Company recall code - **<http://www.bossweb.brp.com>**

Alert number

A12/00541/21

Product

Particle filter mask



Risk type

Health risk / other

The particle/filter retention of the material is insufficient (measured values: as low as $\leq 93\%$). Consequently, an excessive amount of particles or microorganisms might pass through the mask; thus, even if combined with other recommended measures, it may not properly protect.

The product does not comply with the PPE Regulation and the European standard EN 149.

Category

Protective equipment

Type

Consumer

Description

Respiratory protective face mask. The product is also sold online.

Packaging description

The product is sold in a white box with turquoise printing.

Brand

AND MAGPIE

Alert number **[A12/00527/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

The wheel axle may be defective and could break. This will change the steering and driving behaviour, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van / Light commercial vehicle**

Brand **Citroen**

Name **Jumper**

EC-type approval/model **e2*2007/46*0252*, *0254*, *0256*, e3*2001/116*0234*, *0046*, e3*2007/46*0046*, *0051*, Types: YB, YC, YD, Y**

Production dates **The affected vehicles were manufactured between April and June 2019.**

Company recall code **HDW**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **France**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Croatia
Ireland
Poland
Slovenia**

Alert number **[A12/00528/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

The stub axles may be defective and could fracture. This will change the vehicle's steering and driving characteristics, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van / Light commercial vehicle**

Brand **Peugeot**

Name **Boxer**

EC-type approval/model **e2*2007/46*0253*, *0255*, *0257*, e3*2007/46*0045*, *0050*, e2*2001/116*0233*2001/116* , Types: YB, YC, YD, Y**

Production dates **The affected vehicles were manufactured between April and June 2019.**

Company recall code **JYA**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **France**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Croatia
Ireland
Poland
Slovenia**

Alert number **[A12/00531/21](#)**

Product **Motorcycle**

Risk type **Injuries**

The headlamp is fitted with an incorrect bulb that may resonate with the engine vibrations in a certain speed range. Consequently, the filament of the headlamp bulb could break and the headlamp could become unlit, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Motorcycle**

Brand **Suzuki**

Name **GSX250R**

EC-type approval/model **e4*168/2013*00059*00**

Production dates **The affected vehicles were manufactured between 6 February 2017 and 27 February 2018.**

Company recall code **97FF**

Weekly report number **Report-2021-16**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **People's Republic of China**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Germany
Greece**

Alert number **[A12/00529/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

The wheel axle may be defective and could break. This will change the steering and driving behaviour, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van / Light commercial vehicle**

Brand **Fiat**

Name **Ducato**

EC-type approval/model **e3*2007/46*0044*22, Type: 250**

Production dates **The affected vehicles were manufactured between 1 April and 30 June 2019.**

Company recall code **6291**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Poland
Slovenia**

Alert number **[A12/00530/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

The accelerator pedal may be installed incorrectly. As a result, it could become detached, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van / Light commercial vehicle**

Brand **MERCEDES-BENZ**

Name **Sprinter**

EC-type approval/model **e1*2001/116*0354*26, e1*2007/46*0296*14, e1*2007/46*0301*21, e1*2007/46*0304*08, e1*2007/46*1760*04
Types: 906AC35, 906BB50, 906BB35, 906BB50/4x4, KL3A4**

Production dates **The affected vehicles were manufactured between 9 and 12 November 2020.**

Company recall code **VS3FAHPED**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[A12/00536/21](#)**

Product **Lorry**

Risk type **Injuries**

The two screw nuts on the articulation , on vehicles with C2AS suspension, could loosen as a result of an inadequate, non-compliant torque. If they loosen sufficiently, the bolts could fall out, leading to the rear axle connection detaching from the vehicle.

Category **Motor vehicles**

Type **Professional**

Description **Lorry**

Brand **Ford Trucks**

Name **H625 F-Max, H566 Cargo, 4 x 2 Tractor Ford**

EC-type approval/model **Type-approval number: e9*2007/46*0089*19 - e9*2007/46*0089*22, Model: CHK1**

Production dates **05/11/2019 to 30/09/2020**

Company recall code **21S08**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Turkey**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[A12/00550/21](#)**

Product **Passenger car**

Risk type **Fire**

The clutch pedal on the instructor side may be impinging on the wiring harness of the heating/ventilation/air conditioning (HVAC) block. As a result, the ventilation motor will speed up, leading to increased risk of fire.

Category **Motor vehicles**

Type **Professional**

Description **Passenger car - driving school version.**

Brand **PEUGEOT**

Name **208 V2**

EC-type approval/model **e2*2007/46*0639*07, e2*2007/46*0639*08, e2*2007/46*0639*09, e2*2007/46*0639*11, e2*2007/46*0639*12**

Production dates **The affected vehicles were manufactured between 21 February and 14 January 2020.**

Company recall code **KHK**

Weekly report number **Report-2021-16**

Alert submitted by **France**

Is the product counterfeit? **No**

Country of origin **Slovakia**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Date of entry into force **17/02/2021**

Alert number **[A12/00534/21](#)**

Product **Lorry**

Risk type **Injuries**

When the airbag is activated, a defect in the gas generator of the driver airbag may result in uncontrolled inflation and the release of metal fragments, which can cause injury to the occupants.

Category **Motor vehicles**

Type **Professional**

Description **Lorry**

Brand **Mercedes-Benz**

Name **Actros, Antos, Atego**

EC-type approval/model **Type approval numbers: e1*2007/46*0726, *0727, *0732, *0733, *0734, *0735, *0736, *1170,*1172
Type: 963-0-A, 963-4-A, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 967PKX2, 967SZX3**

Production dates **From 01/10/2011 to 31/07/2012**

Company recall code **TAKA-DIODE**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Greece
Poland**

Alert number **[A12/00535/21](#)**

Product **Lorry**

Risk type **Injuries**

When the airbag is activated, a defect in the gas generator of the driver airbag may result in uncontrolled inflation and the release of metal fragments, which can cause injury to the occupants.

Category **Motor vehicles**

Type **Professional**

Description **Lorry**

Brand **Mercedes-Benz**

Name **Actros, Antos, Arocs, Atego**

EC-type approval/model **Type approval numbers: e1*2007/46*0726, *0727, *0732 - *0737, *1170 - *1172, *1174 - *1176, *1650, *1651
Type: 963-0-A, 963-4-A, 963-0-C, 963-4-D, 963-4-C, 963-0-D, 963-7-E, 963-4-E, 967PKX2, 967PKX3, 967SZX3, 967KMU3, 967FWU2, 967FWU3, 967PKX3-T, 967PKX2-T**

Production dates **From 01/08/2012 to 01/10/2017**

Company recall code **TAKA-SDI**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and **Greece
Poland**

Alert number **[A12/00532/21](#)**

Product **Plush toy**



Risk type **Choking**

A small part can detach (eye of the bear). A small child can put it in the mouth and choke on it.

The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Category **Toys**

Type **Consumer**

Description **Plush toy in the shape of a bear.**

Packaging description **Packed in a plastic bag.**

Brand **Catchi**

Name **Kiekeboe Beer NEDERLANDS gesproken**

Barcode **7061251693079**

Weekly report number **Report-2021-16**

Alert submitted by **The Netherlands**

Is the product counterfeit? **No**

Country of origin **People's Republic of China**

Alert number

[A12/00542/21](#)

Product

Particle filter mask



Risk type

**Health risk / other
Microbiological**

The particle/filter retention of the material is insufficient (measured values: 92%). Consequently, an excessive amount of particles or microorganisms might pass through the mask; thus, even if combined with other recommended measures, it may not properly protect.

EN 149, Clause 7.9.1 Regulation (EU) 2016/425

Category

Protective equipment

Type

Consumer

Description

20 individually packed face masks

Packaging description

Blue and white cardboard box

Brand

Highlight

Name

Daily Protective Face Mask

Type / number of model

KN95/FFP2

Barcode

4064011489489

Weekly report number

Report-2021-16

Alert submitted by

The Netherlands

Alert number

A12/00543/21

Product

Children's high chair set



Risk type

Injuries

The high chair is not sufficiently stable and can easily tip over backwards. A child using the high chair may fall and suffer injuries.

The product does not comply with the requirements of the General Product Safety Directive and with the relevant European standard EN 14988.

Category

Childcare articles and children's equipment

Type

Consumer

Description

Children's high chair composed of two parts, which can also be used separately as a table and high chair. The product is made of white and red plastic. The seat and back of the chair are covered with washable material. The counter on the chair can be removed.

Packaging description

The product is stored in a cardboard package in an unfolded state.

Alert number **[A12/00547/21](#)**

Product **Passenger car**

Risk type **Injuries**

The ground connection of the passenger airbag may be inadequate and any electrostatic charge might not be conducted away through it. As a result, the passenger airbag could be triggered unnecessarily even if it has been properly deactivated because a child seat is being used on the passenger seat. This could lead to an increased risk of accident or injury.

Category **Motor vehicles**

Type **Consumer**

Description **Model series BR 247.**

Brand **Mercedes-Benz**

Name **GLA**

EC-type approval/model **e1*2007/46*1909*06 , Type: F2B**

Production dates **The affected vehicles were manufactured between 19 February 2020 and 12 August 2020.**

Company recall code **9193003**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and **Greece
Poland**

Alert number **[A12/00546/21](#)**

Product **Passenger car**

Risk type **Injuries**

The surface of the instrument panel might not be adequately bonded to the base support. As a result, the opening behaviour of the passenger airbag could be impaired, increasing the risk of injury in the event of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Model series: BR 167.**

Brand **Mercedes-Benz**

Name **GLE, GLS**

EC-type approval/model **e1*2007/46*1885*03 - *09; Type: H1GLE**

Production dates **The affected vehicles were manufactured between 15 October 2018 and 4 September 2020.**

Company recall code **8192003**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code **- <http://www.Mercedes-Benz.de>**

Alert number **[A12/00554/21](#)**

Product **Motorcycle**

Risk type **Injuries**

During the production assembly process, the left cushion connecting plate was installed with the inside and outside reversed, which may cause an excessive load to be applied to it. As a result, the plate could break, causing a sudden drop in ride height and leading to increased risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Model code: SC82 (CBR1000SPL/STL); Model type: CBR1000SPL/STL (2ED, ED); Model year: 2020.**

Brand **Honda**

Name **CBR1000 SPL/STL**

EC-type approval/model **e4*168/2013*00126*00**

Production dates **The affected vehicles were manufactured between 9 December 2019 and 3 June 2020.**

Company recall code **3LS**

Weekly report number **Report-2021-16**

Alert submitted by **Portugal**

Is the product counterfeit? **No**

Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Importer**

Products were found and **France
Poland**

Alert number **[INFO/00099/21](#)**

Product **Passenger car / Light commercial vehicle**

Risk type **Injuries**

Moisture may ingress into the wiring harness for the rear-view camera system. As a result, the rear hatch mechanism may open inadvertently, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car / Light commercial vehicle**

Brand **MERCEDES-BENZ**

Name **Citan**

EC-type approval/model **Type-approval numbers: e2*2007/46*0129*13 - *14, e2*2007/46*0129*16 - *22, e2*2007/46*0129*24 - *28, e2*2007/46*0130*13, e2*2007/46*0130*15 - *21, e2*2007/46*0130*24 - *28
Type: X**

Production dates **The affected vehicles were manufactured between 25 February 2015 and 16 November 2020.**

Company recall code **C1HECKLAP (7493051)**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **France**


Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number

A12/00556/21

Product

Particle filter mask



Risk type

Health risk / other

The particle/filter retention of the material is insufficient (measured values: as low as 53%). Consequently, the product does not fulfil the health and safety requirements; thus, even if combined with other recommended measures, it may not properly protect.

The product does not comply with the PPE Regulation and with the relevant European standard EN 149.

Category

Protective equipment

Type

Consumer

Description

Particle filter mask, labelled as "for children". The product is also sold online, in particular via eBay.

Packaging description

The product is sold in transparent-and-blue plastic pouches, containing each 10 pieces.

Brand

SHUFANG

Alert number

[A12/00545/21](#)

Product

Children's clothing set



Risk type

**Injuries
Strangulation**

The products bear cords with free ends in the hood area and in the waist area. The cords may become trapped during various activities of a child, leading to injuries and/or strangulation.

The product does not comply with the requirements of the General Product Safety Directive and with the relevant European standard EN 14682.

Category

Clothing, textiles and fashion items

Type

Consumer

Description

The set consists of an orange sweatshirt with hood and trousers, intended for children aged between 5 and 6 years old, with free ends cords.

Packaging description

Transparent plastic bag.

Brand

ARANDY & STORE

Type / number of model

Size 5-6 years

Barcode

8685966584522

Weekly report number

Report-2021-16

Alert submitted by

Romania

Alert number **[A12/00549/21](#)**

Product **Passenger car**

Risk type **Injuries**

The seams of the passenger airbag may split when the airbag inflates. This will increase the risk of injury in the event of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger car**

Brand **Mazda**

Name **MX-30**

EC-type approval/model **e13*2007/46*2300*00 - *02, Type DR**

Production dates **The affected vehicles were manufactured between 19 May and 24 November 2020.**

Company recall code **AM020A**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**


Country of origin **Japan**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Company recall code **- <https://www.mazda.de/service-zubehoer/rueckrufaktionen/>**

Alert number **[A12/00544/21](#)**

Product **Children's clothing set**



Risk type	Injuries Strangulation
	The products bear cords with free ends in the hood area and in the waist area. The cords may become trapped during various activities of a child, leading to injuries and/or strangulation.
	The product does not comply with the requirements of the General Product Safety Directive and with the relevant European standard EN 14682.
Category	Clothing, textiles and fashion items
Type	Consumer
Description	The set consists of a red sweatshirt with hood and trousers, size 98, with free ends cords.
Packaging description	Transparent plastic bag.
Brand	WIYAN KIDS CLUB
Type / number of model	Size 98
Weekly report number	Report-2021-16
Alert submitted by	Romania
Is the product counterfeit?	Unknown
Country of origin	Turkey

Alert number **[A12/00553/21](#)**

Product **Lorry**

Risk type **Injuries**

In the steering shaft, a friction weld was over-turned and it may fail, letting substances penetrate. Consequently, it could cause cracks in the weld and a loss of steering control, leading to an accident and injuries to the users.

Category **Motor vehicles**

Type **Professional**

Description **Lorry**

Brand **MAN**

Name **TGM, TGS, TGX**

EC-type approval/model **Models: L.2007.46.001, L.2007.46.010, L.2007.46.002
Type-approval numbers: e4*2007/46*0229*37-*38,
e4*2007/46*0229*40, e4*2007/46*0238*38,
e4*2007/46*0230*38**

Production dates **October 2019 to January 2021**

Company recall code **7453TR**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Alert number **[A12/00555/21](#)**

Product **Motorcycle**

Risk type **Injuries**

The valve guides may have quality issues that could lead to excessive wear of the engine components. Consequently, this excessive wear can lead to engine failure, which may increase the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Ducati Multistrada V4S, model year: 2021**

Brand **Ducati**

Name **Multistrada V4S**

EC-type approval/model **e9*168/2013*11661*00**

Production dates **Model Year: 2021**

Company recall code **CR208**

Weekly report number **Report-2021-16**

Alert submitted by **Poland**

Is the product counterfeit? **Unknown**

Country of origin **Italy**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**

Products were found and measures were taken also in **Greece
Ireland
Slovenia**

Alert number **[A12/00548/21](#)**

Product **Passenger van / Light commercial vehicle**

Risk type **Injuries**

The Electronic Stability Program (ESP) control unit may cut out under certain circumstances. This will impair the driving stability, increasing the risk of an accident.

Category **Motor vehicles**

Type **Consumer**

Description **Passenger van / Light commercial vehicle**

Brand **Mercedes-Benz**

Name **Sprinter**

EC-type approval/model **Types: 906BA50, 906BB50, 906BB50, 906BB50/4x4, 906BB50/4x4, 906BA50/4x4, e1*2007/46*0294*02 - *08, e1*2007/46*0295*04 - *09, e1*2007/46*0295*11, e1*2007/46*0296*01 - *08, e1*2007/46*0304*01 - *05, e1*2007/46*0307*03, e1*2007/46*0307*06 - *08, e1*2007/46*0308*02 - *05**

Production dates **The affected vehicles were manufactured between 4 January 2012 and 25 October 2018**

Company recall code **NC3DREZAHA (4391084)**

Weekly report number **Report-2021-16**

Alert submitted by **Germany**

Is the product counterfeit? **No**

Country of origin **Germany**

Measures taken by economic operators **Recall of the product from end users
Manufacturer**